

AUTOMATIC FEED GLASSWASHING

Topmatic Crystal GB Special & Toprinse Crystal

HS/TC/041/03 – August 2017



READ BEFORE STARTING

Wear PPE in each step

FOR PPE SEE BELOW



You MUST refer to the CPAs & Task Cards for your PPE Requirements


1 Undo cap on empty bottle and carefully remove feed pipe




2 Remove empty bottle and replace with new bottle



3 Undo cap on new bottle and carefully place in feed pipe



4 Tighten cap



5 Place new cap on old bottle and dispose of or recycle



TOPRINSE CRYSTAL   
Safety glasses with side-shield & Gloves

TOPMATIC CRYSTAL GB SPECIAL 
Not a hazardous substance or mixture.